

ARRIVAL ROUTE DESCRIPTION

From KOOLY via 287° track to SQUEZ, cross SQUEZ between 12000 and 15000 at 250K, then via 289° track to CABOS, cross CABOS between 10000 and 12000, thence as depicted on runway transitions.

RWYS 7L, 7R, 8 TRANSITIONS: From CABOS 289° track to MATRE, cross MATRE at 10000, then via 289° track to BASHA, cross BASHA at 9000 and at 210K, then via 289° track to BRNDA, cross BRNDA at 7000 at 210K, then via 258° track to NEELE, then via 258° track. Expect ILS approach or RADAR vectors to final approach course.

RWY 25L TRANSITION: From CABOS 323° track to PUKRE, cross PUKRE between 8000 and 9000 at 210K, then via 322° track to FINAP, cross FINAP between 5000 and 6000, then via 282° track to GIPSE, cross GIPSE at or above 4000. Expect ILS approach or RADAR vectors to final approach course.

RWY 25R TRANSITION: From CABOS 323° track to PUKRE, cross PUKRE between 8000 and 9000 at 210K, then via 322° track to FINAP, cross FINAP between 5000 and 6000, then via 284° track to ZAMEX, cross ZAMEX at or above 4000. Expect RNAV (GPS) approach or RADAR vectors to final approach course.

RWY 26 TRANSITION: From CABOS 323° track to PUKRE, cross PUKRE between 8000 and 9000 at 210K, then via 322° track to FINAP, cross FINAP between 5000 and 6000, then via 292° track to JAGAL, cross JAGAL at or above 4000. Expect ILS approach or RADAR vectors to final approach course.

LOST COMMUNICATIONS

Landing Rwy 7L: At NEELE turn right, intercept and execute RWY 7L ILS approach. If unable, proceed direct PXR VORTAC and hold, maintain 9000.

Landing Rwy 7R: At NEELE turn right, intercept and execute RWY 7R ILS approach. If unable, proceed direct PXR VORTAC and hold, maintain 9000.

Landing Rwy 8: At NEELE turn right, intercept and execute RWY 8 ILS approach. If unable, proceed direct PXR VORTAC and hold, maintain 9000.

Landing Rwy 25L: At GIPSE intercept and execute RWY 25L ILS approach. If unable, proceed direct PXR VORTAC and hold, maintain 9000.

Landing Rwy 25R: At ZAMEX intercept and execute RWY 25R RNAV (GPS) approach. If unable, proceed direct PXR VORTAC and hold, maintain 9000.

Landing Rwy 26: At JAGAL intercept and execute RWY 26 ILS approach. If unable, proceed direct PXR VORTAC and hold, maintain 9000.